

Alaska Railroad Corporation
Summary List of Suspect Asbestos Materials

Site: Anchorage
Bldg ID: Lease Property-900 East Whitney Road Real Estate
900 East Whitney Road
Anchorage, AK

HM	Material Description	Floor	Location(s)	Contains Asbestos	Lab Results
1	Miscellaneous, unknown		unknown	unknown	
2	Drywall, Drywall		Entryway at north entrance	YES	5-10% Chrysotile
3	Cove base and mastic, Cove base and mastic		Bathroom	NO	
4	Sheet vinyl and mastic, Sheet vinyl (beige) and mastic		Bathroom flooring	NO	
5	Concrete, Concrete floor/foundation		Main floor/foundation	NO	

Table 1 - Asbestos Bulk Sample Analytical Results

920 East Whitney Road
Anchorage, Alaska

Sample	Layer	Material	Color	Location	Estimated Extent	Asbestos Content in Percent by PLM
S1	1 of 1	Insulation foam	Tan/Yellow	Back room ceiling	4,500 ft ²	ND
S2	1 of 1	Wallboard/Paper	White	Back room ceiling	4,500 ft ²	ND
S3	1 of 2	Wallboard/mud	White	Back room ceiling		<1
	2 of 2	Wallboard/Paper	White	Back room ceiling		ND
S4	1 of 2	Wallboard/mud	White	Back room ceiling		<1
	2 of 2	Wallboard/Paper	White	Back room ceiling		ND
S5	1 of 1	Wallboard/Paper	Tan	Loading dock wall	100 ft ²	ND
S6	1 of 1	Wallboard/tape/mud	Tan	Main warehouse wall	600 ft ²	ND
S7	1 of 1	Window Caulk	Black	Side and front windows	200 ft	ND
S8	1 of 2	Cove Base	Black	Front main warehouse wall	100 ft	ND
	2 of 2	Mastic	Dark Brown	Main warehouse wall		ND
S9	1 of 4	Wallboard/tape/mud	Cream	Northeast Main warehouse wall	100 ft ²	ND
	2 of 4	Wallboard	Off-White	Northeast Main warehouse wall		ND
	3 of 4	Wallboard/Paper	Off-White	Northeast Main warehouse wall		ND
	4 of 4	Wallboard/Paper	White	Northeast Main warehouse wall		ND
S10	1 of 2	Cove Base	Black	Front Wall	100ft	ND
	2 of 2	Mastic	Dark Brown	Front Wall		ND
S11	1 of 2	Carpet	Green	Kitchen floor	100 ft ²	ND
	2 of 2	Mastic	Cream	Kitchen floor		ND
S12	1 of 1	1-ft x 1-ft ceiling panel	White	Kitchen ceiling	100 ft ²	ND
S13	1 of 2	Wallboard/tape/mud	Off-White	Kitchen	250 ft ²	ND
	2 of 2	Wallboard/Paper	White	Kitchen		ND
S14	1 of 2	Linoleum	Tan	Storage room	25 ft ²	ND
	2 of 2	Mastic	Gray	Storage room		ND
S15	1 of 2	Cove Base	Black/Blue	Storage room	20 ft	ND
	2 of 2	Mastic	Dark Brown	Storage room		ND
S16	1 of 3	Wallboard	White/Cream	Storage room	140 ft ²	ND
	2 of 3	Wall texture	White	Storage room		ND
	3 of 3	Wallboard/Paper	White	Storage room		ND
S17	1 of 2	Linoleum	Tan	Bathroom	25 ft ²	ND
	2 of 2	Mastic	Gray	Bathroom		ND
S18	1 of 1	Wallboard/tape/mud	White	Bathroom	140 ft ²	ND
S19	1 of 2	Cove Base	Blue	Bathroom	20 ft	ND
	2 of 2	Mastic	White	Bathroom		ND

Removed
Abated
Sep 2013

Notes:

ND = Not detected; method reporting limit is 1 percent.

PLM = Polarized Light Microscopy.

sf = Square feet.

Hart Crowser

8975

Table 2 - Lead Screening Results
920 East Whitney Road
Anchorage, Alaska

Sample	Substrate	Color	Location	Field Screening Results
P1	Concrete floor	Pea green	Main warehouse	Negative
P2	Concrete floor	Gray	Shop area	Negative
P3	Metal Siding	Orange	Exterior walls	Negative
P4	Metal door	Gray/White	Side man door	Negative
P5	Concrete foundation	Pea Green	Interior perimeter	Negative
P6	Plywood and plasterboard	White	Spray room walls	Negative
P7	Plywood and plasterboard	Multi-Colored	Spray room walls	Negative
P8	Plywood and plasterboard	Tan	Main warehouse walls	Negative
P9	Plywood and plasterboard	Tan	Main warehouse walls	Negative

Notes:
 Screening by *LeadCheck* PB-2m161

Hart Crowser
 8975